

M. Callanan Plant

DELIVERY / EXCHANGE / COLLECTION NOTE

54 DENECROFT CRESCENT, HILLINGDON, MIDDLESEX
 Tel: 07957 756 234 • 07836 680 360 • Acc/Office: 07964 421 614
 Email: callananplanthire@hotmail.com



Y668 GYK

CUSTOMER: *Hickey*
 SITE ADDRESS

DATE: *11/05/21 - Hire Start 12/05/21*
 MACHINE TYPE: *NC SW6*
 SERIAL NO: *49912*
 HOURS:

Collected for CPH

MARK DAMAGE WITH X



EXCAVATORS

BUCKETS

- 6 inch/150 mm
- 9 inch/225 mm
- 12 inch/300 mm
- 18 inch/450 mm
- 24 inch/600 mm
- 30 inch/750 mm
- 36 inch/900 mm
- 42 inch/1050 mm
- 54 inch/1350 mm
- DITCH
- OTHER

- WINDOWS
- DOORS
- PANELS
- RAMS
- RAM GUARDS
- LIGHTS
- BEACONS
- REFUEL PUMP
- COUPLINGS

FUEL E 1/4 1/2 3/4 F

- QUICK HITCH
- SAFETY BAR
- LEVER (Q/H)
- GREASE GUN
- MIRRORS
- TANK CAPS
- TRACKS
- KEYS
- HOSES

BREAKERS

PINS RETAINERS CHISEL HOSES

DUMPERS

- PANELS
- TYRES
- ROPS

- BEACONS
- SEAT
- SEAT BELT
- RAMS

- SKIP
- LIGHTS
- KEYS
- G/GUN
- TYRES
- HANDBRAKE

FUEL E 1/4 1/2 3/4 F

WARNING! DAMAGE DUE TO DIRTY DIESEL/WATER WILL BE CHARGED FOR.

Any damage to tracks will be charged. Concrete splashes will be charged to be removed.

Please receive on hire plant/equipment as detailed subject to our terms and conditions of hire (C.P.A. Conditions), a copy of which is available on request.

1. Acceptance of plant on site includes acceptance of our terms and conditions.
2. Puncture repairs are the responsibility of the hirer.
3. Any item not returned or returned in a damaged condition will be charged to the hirer, including repair of tyres punctured/damaged on site.
4. You are responsible for the supply of all fuels and lubricants.
5. Lubrication must be carried out regularly and properly in accordance with manufactures recommendations. Damage resulting from lack of or incorrect lubrication will be charged to the hirer.
6. You are to insure for full replacement value & continuing hire charges, you & your insurers are responsible for any loss or damage.

COMMENTS: *Good working ORDER.*

ALL PLANT WILL UNDERGO A FULL INSPECTION ON RETURN TO DEPOT.

SIGNED BY THE HIRER *[Signature]*

PRINT NAME *[Signature]*