



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	DB1 KOMATSU	Date:	21/04/2026
Fleet Number	H272	PI	
Hour Meter	3408 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due ? hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	✓		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	✓		Electric		
Bodywork	✓		Cable Connections	✓	
Operating Controls	✓		General Cleanliness	✓	
Warning Lights	✓		Battery Security	✓	
Gauges/Instruments	✓				
Railings / boxing ring	N/A		Other Checks		
Fan & other belts / chains	✓		Front left wheels		
Fuel cap secured	✓		Front right wheels		
Lenses & mirrors	✓		Rear left wheels		
Rear & 360° cameras	✓		Rear right wheels		
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Defects / Service Details / Notes  
 AND CREAMED OR OIL  
 ALL CHECKED OVER, ALL GREASES AROUND, ALL IN WORKING ORDER

Engineers name: JC  
 Signature: [Signature]