



H219

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X225-G	Date:	24/3/2025.
Fleet Number	219		
Hour Meter	5358 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due 5777 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	✓	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	NA	
Seat & Seat Belt	✓	
Steering if applicable	NA	
Brakes as appropriate	NA	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	✓	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	✓	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Steer sensor damaged (wires broken)

Defects / Service Details / Notes
All checks done, cleaned all round, greased all round.
All in working order.

Engineers name: *Jonny Croft* Signature: *[Signature]*