



H221

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x130-6	Date:	24/3/2025.
Fleet Number	221		
Hour Meter	5590 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 6012 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	X	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	NA	
Seat & Seat Belt	✓	
Steering if applicable	NA	
Brakes as appropriate	NA	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	✓	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	✓	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

4x Top rollers changed.

Defects / Service Details / Notes  
 All checks done, cleaned inside/outside, greased,  
 All in working order.

Engineers name: Iona, C. Gabriel N.	Signature: [Signature]
--	---------------------------