



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x35-6	Date:	26/3/2025
Fleet Number	280		
Hour Meter	1856 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 2216 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	NA		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	NA	
Blade / stabilizers if fitted	✓				
Seat & Seat Belt	✓				
Steering if applicable	NA				
Brakes as appropriate	NA				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	✓				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	NA				
Lights / Beacons	✓				
Obvious Leaks	✓				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes  
*All checks done, cleaned all round, greased all round.  
 All in working order.*

Engineers name: *Ionan C* Signature: *[Signature]*